




Figure 4-1
CSMRI Surface Survey Gamma Radiation Distribution
Represented by Block Kriging with Linear Drift



Gamma Meter
Counts per Minute

LEGEND

- Fenceline
- Break in Slope
- Building Outline



New Horizons Environmental Consultants, Inc. 6585 South Wright Street Littleton, CO 80127-4806		
		Project: CSMRI Remedial Investigation
Project Number: 2112	Figure 4-1 CSMRI Surface Survey Gamma Distribution Represented by Block Kriging with Linear Drift	