



**LEGEND**

- ⊕ Existing Monitoring Well
- ⊙ Abandoned Monitoring Well
- ⊗ Proposed Monitoring Well
- Surface-Water Sample Location

**Figure 1** Ground- and Surface Water Monitoring Locations

**Project:** CSMRI Site Remediation

**Project Number:** 2135     **Date:** March 28, 2004



**New Horizons Environmental Consultants, Inc.**  
 6585 South Wright Street  
 Littleton, CO 80127-4806