


# Figure 3-1 Gamma Survey Locations



Notes: A small number of points appear outside the fence or out of position because of GPS interference or unavailable differential correction files during that portion of the gamma survey.

	<b>New Horizons Environmental Consultants, Inc.</b> <b>6585 South Wright Street</b> <b>Littleton, CO 80127-4806</b>	
Project: CSMRI Remedial Investigation		Date: October 15, 2003
Project Number: 2112	Figure 3-1 Gamma Survey Locations	