


Figure 3-2
Clay Pits and Background Gamma Survey Points



New Horizons Environmental Consultants, Inc.
6585 South Wright Street
Littleton, CO 80127-4806

Project: CSMRI Remedial Investigation

Date: October 15, 2003

Project Number: 2112

Figure 3-2 Clay Pits and Background Gamma Survey Points