



Figure 3-3 CSMRI Surface Soil Sample Locations



LEGEND

- - - Fenceline
- - - Break in Slope
- Building Outline
- x Surface Sample



New Horizons Environmental Consultants, Inc. 6585 South Wright Street Littleton, CO 80127-4806	
Project: CSMRI Remedial Investigation	Date: October 15, 2003
Project Number: 2112	Figure 3-3 Surface Soil Sample Locations