




**Figure 4-11  
Test Pit Samples  
Variation of Concentration with Depth - Arsenic and Lead**

**Variation of Concentration with Depth  
in Vicinity of Building 101  
(Includes Test Pits CP18 through CP27)**




**Variation of Concentration with Depth  
other Test Pit Sites  
(Includes Test Pits CP3 - CP17 & CP28 - CP36)**



**LEGEND**

- Fenceline
- Break in Slope
- Building Outline
- Test Pit Location



Notes: Lognormal distribution assumed for calculation of average concentration. Small sample sizes (<30) were used for calculations. Different scales used for graphs.

 **New Horizons Environmental Consultants, Inc.**  
6585 South Wright Street  
Littleton, CO 80127-4806

Project: CSMRI Remedial Investigation      Date: October 15, 2003

Project Number: 2112      Figure 4-11 Test Pit Samples - Variation of Concentration with Depth - Arsenic and Lead