




Figure 4-2
Surface Soil Samples
Arsenic Concentrations



New Horizons Environmental Consultants, Inc.
6585 South Wright Street
Littleton, CO 80127-4806

| | |
|---------------------------------------|------------------------|
| Project: CSMRI Remedial Investigation | Date: October 15, 2003 |
|---------------------------------------|------------------------|

| | |
|----------------------|--|
| Project Number: 2112 | Figure 4-2 Surface Soil Samples Arsenic Concentrations |
|----------------------|--|