

Figure 4-2
CSMRI Surface Soil Samples
Arsenic Concentrations





Note: Background color variations represent surface gamma distribution generated by geostatistics (kriging).



New Horizons Environmental Consultants, Inc. 6585 South Wright Street Littleton, CO 80127-4806

Project: CSMRI Remedial Investigation

Date: October 15, 2003

Project Number: 2112

Figure 4-2 CSMRI Surface Soil Samples Arsenic Concentrations